Form No. 2-A
Rev. 10/71

Locomotive Number 60

Initials PHD

PORT HURON AND DETROIT RAILROAD COMPANY

LOCOMOTIVE INSPECTION REPORT

Instructions: Each locomotive must be inspected after each trip or day's work and report made on this form whether needing repairs or not. Proper explanation must be made hereon for failure to repair any defect reported, and the form approved by foreman, before the locomotive is returned to service.

Inspected at P. Huron Time 1705 Date 3-21-83

Repairs needed:

Gene Ogden Collection

Condition of brakes and brake rigging Good

Main reservoir pressure 140 pounds. Brake-pipe pressure 70 pounds

(Signature) C Brennan

(Occupation) Engr

The above work has been performed, except as noted, and the report is approved.

Foreman