

Locomotive Number 62

Initials PHD

PORT HURON AND DETROIT RAILROAD COMPANY

LOCOMOTIVE INSPECTION REPORT

Instructions: Each locomotive must be inspected after each trip or day's work and report made on this form whether needing repairs or not. Proper explanation must be made hereon for failure to repair any defect reported, and the form approved by foreman, before the locomotive is returned to service.

Inspected at Port Huron Time 1820 Date 8-16-83

Repairs needed:

Multiple horizontal lines for reporting repairs needed.

Gene Ogden Collection

Condition of brakes and brake rigging Good

Main reservoir pressure 140 pounds. Brake-pipe pressure 20 pounds

(Signature) C. Brennan

(Occupation) Eng.

The above work has been performed, except as noted, and the report is approved.

Foreman